



Manifold Absolute Pressure/Pressure Sensor Wiring Terminations			
<b>1, 2 &amp; 3 Bar MAP</b>			
	<b>Gnd/Rtn</b>	<b>+5V</b>	<b>Signal</b>
Terminal Location in Connector	A	C	B
Connect to BS3 Harness Wire Color	<b>Black</b>	<b>Red</b>	<b>White/Blue</b>
<b>3 Bar MAP</b>			
	<b>Gnd/Rtn</b>	<b>+5V</b>	<b>Signal</b>
Terminal Location in Connector	A	C	B
Connect to BS3 Harness Wire Color	<b>Black</b>	<b>Red</b>	<b>White/Blue</b>
<b>4 Bar MAP</b>			
	<b>Gnd/Rtn</b>	<b>+5V</b>	<b>Signal</b>
Terminal Location in Connector	A	B	C
Connect to BS3 Harness Wire Color	<b>Black</b>	<b>Red</b>	<b>White/Blue</b>
<b>150 PSI Pressure Sensor</b>			
	<b>Gnd/Rtn</b>	<b>+5V</b>	<b>Signal</b>
Terminal Location in Connector	A	B	C
Connect to BS3 Harness Wire Color	<b>Black</b>	<b>Red</b>	<b>White/Blue</b>